

 **ACC2 socket format change (It only matters if you intend to use the optional antenna selector)**

Due to component discontinuation, starting with serial # 09353001 for AR5001D and # 09441001 for AR6000, the ACC2 socket on the receiver back panel has been changed from Mini-DIN to the RJ45 format.

In clear, if you intend to use the optional antenna selector, do not use the AS5001 model, but **AS5700**.